ARTEMIS GOLD INC | Blackwater Mine

90 Day Follow-up Report

July 25, 2026

Subject: 90 Day Follow-up Report – IECD Pipeline Leak

Dear sir(s) and madam(s):

As per Blackwater Gold's Accidents and Malfunctions Management Plan (AMCP) and Mine Emergency Response Plan (MERP), BW Gold Ltd is providing this notification to satisfy the 90-Day Follow-up Report requirement of an accident or malfunction.

At approximately 17:00 on April 26, 2026, a leak was discovered from a subsurface pipeline running from the Interim Environmental Control Dam (IECD) to the Blackwater Mill, at 10U 376088 5895477. The IECD collects process water seepage from the Tailings Storage Facility (DGIR #261570). Upon discovery, pumping through the line was terminated; the pipeline has since been repaired.

Monitoring has continued to occur downstream of the spill and the most recent results for parameters that initially exceeded the BCWQG's are shown below:

Table 1. Site 661-05 Sample Results

		Location	661-05	661-05	661-05
		Sample Date	2026-05-01	2026-05-27	2026-06-21
Parameter	**BCWQG AWF LT Chronic**	**Unit**	**Result**	**Result**	**Result**
D-Cobalt	0.00039	mg/L	0.00260	0.00151	0.00100
T-Aluminum	0.245	mg/L	0.507	0.144	0.111

Total Aluminum and Dissolved Cobalt concentrations have declined steadily since the release was identified. While Dissolved Cobalt remains above the BCWQG, Total Aluminum has fallen below the guideline threshold. Monitoring at this location is ongoing, with results being evaluated by a Qualified Professional.

Following the incident, the following corrective actions have been implemented to prevent reoccurrence:

- Implement pressure testing or other leak detection methods for contact water piping systems.
- Utilize site CMMS system for all work orders on piping to ensure traceability of work carried out. This includes the person responsible for the work and any notes related to the work, such as start and completion dates.
- Develop Management of Change (MoC) Procedure for design changes to ensure adequate implementation, and verification of previous design tasks and repair, when and as required.

No additional views from Indigenous Groups or advice from relevant authorities were received regarding the incident.

Please do not hesitate to contact the undersigned if there are any further questions.

Kind regards,

Mark Warbanski

Mark Warbanski
Environment Manager
BW Gold Ltd.